National Transportation Safety Board
FACTUAL REPORT
AYIATION

NTSB ID: LAX01LA181

Aircraft Registration Number: N2479S

Occurrence Date: 05/18/2001

Most Critical Injury: None

Occurrence Type: Accident

Investigated By: NTSB

Location/Time

Aims out Duovinsitus Off A: 1/A: 1:	Distance From	m Landing Facility:			
Paauilo	HI	96764	0816	HST	
Nearest City/Place	State	Zip Code	Local Time	Time Zone	

Airport Proximity: Off Airport/Airstrip Distance From Landing Facility:

Aircraft Information Summary

Aircraft Manufacturer	Model/Series	Type of Aircraft
Cessna	337C	Airplane

Revenue Sightseeing Flight: Yes Air Medical Transport Flight: No

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On May 18, 2001, at 0816 Hawaiian standard time, a Cessna 337C, N2479S (Mokulele 3), experienced a loss of engine power in both engines and ditched in the ocean off the coast of Paauilo, Hilo, Hawaii. Mokulele Flight Service, Inc., owned and operated the airplane under the provisions of 14 CFR Part 135 as an on-demand air taxi flight. The tour flight, Circle Island Flight, was a counter clockwise tour around the big island. The commercial pilot and five passengers were not injured. The airplane sank in deep water, 150 feet, and presumed to be destroyed. Visual meteorological conditions prevailed for the local area sightseeing flight, and a company visual flight rules (VFR) flight plan had been filed. The flight departed the Kona International Airport, Keahole (KOA), Kailua/Kona, Hawaii, at 0700. The flight was scheduled to terminate at KOA.

According to Hilo Air Traffic Control (ATC) personnel, radar services were terminated with the accident airplane about 0806 after the airplane had transitioned through the Hilo terminal area. The pilot was instructed to squawk VFR and a frequency change was approved. The pilot switched to a UNICOM frequency.

At 0814, a company pilot reported to Hilo ATC that he had heard a mayday call on the UNICOM frequency. He indicated that a company airplane had crashed into the water abeam Paauilo.

In the pilot's written statement, he indicated that he conducted a preflight inspection of the airplane that included a weather check, weight and balance, and inspection of the airplane. Once everyone boarded the airplane, he conducted engine run-ups with all gages, including the fuel gages indicating normal. The flight departed on the main fuel tanks, and were kept in that position throughout the duration of the flight.

Near Paauilo, both engines started to fluctuate with a gradual power reduction. The pilot started the emergency procedures, advanced the mixtures, propellers, and throttles. He expected that one of the engines would have a greater surge, but that was not the case. He reported that the front engine was "going in and out of power." He checked the fuel pressure gages and saw that both needles indicated zero. He turned on both fuel boost pumps and checked that the magnetos were on both. There was no response. He then made several unsuccessful attempts to get a "fuel flow response" by switching both sets of fuel selectors to "various settings."

Once the pilot was unable to deduce the nature of the problem, he realized that they were losing altitude. He turned his attention to his passengers and briefed them again on the emergency procedure for an ocean ditching. He reached over and opened the emergency exit door, made a mayday call, and then landed straight ahead. He felt the safest place to land was the ocean due to the calm and smooth conditions.

The pilot stated that the airplane bounced twice before the final impact. The front windscreen collapsed on the final impact and the cockpit started to fill with water. The pilot exited through

National Transportation Safety Board FACTUAL REPORT

AVIATION

NTSB ID: LAX01LA181

Occurrence Date: 05/18/2001

Occurrence Type: Accident

Narrative (Continued)

the front of the airplane. When he surfaced he saw that two passengers were at the surface inflating their life vests. The pilot swam to the right front of the airplane where he saw a third passenger surface. He then dove to the door, which was submerged, to assist the last passenger who was still in the airplane. The airplane was starting to sink, and he was unable to reach the passenger. The pilot resurfaced, and then saw the last passenger surface.

A tour helicopter circled the area and dropped life preservers. Personnel from county rescue services had everyone out of the water and to the nearest hospital 15 minutes after the accident.

Federal Aviation Administration (FAA) inspectors interviewed the pilot and passengers. The pilot and passengers reported that both engines quit at the same time. The pilot told the FAA that he did not visually verify the fuel quantity; instead he utilized the fuel gages as a reference for fuel quantity. The pilot further reported that he believed there were several gallons of fuel in the auxiliary tanks. When the engines quit, he switched to the auxiliary tanks, with no change in the loss of engine power.

The FAA inspectors also interviewed the owner, refueler, and director of maintenance of the company. The airplane was refueled the previous night with 44 gallons of fuel. When the refueler visually checked the fuel level, he stated that the fluid was just below the top, about 1 inch, which should have been 75 gallons. There were no unresolved mechanical anomalies with the airplane prior to the accident flight.

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: LAX01LA181

Occurrence Date: 05/18/2001

AVIATION		Occurrence Type: Accident								
Landing Facility/Approach In	formation	•								
			port ID:	Airport Elevation	Run	way Used	Runwa	y Length	n Run	way Width
				Ft. MSL	. NA					
Runway Surface Type: Unknown										
Runway Surface Condition: Unknown	own									
•										
Approach/Arrival Flown: NONE										
VFR Approach/Landing: Forced L	anding									
Aircraft Information										
Aircraft Manufacturer			Model/					Serial N		
Cessna			337C					337-0	779 ———	
Airworthiness Certificate(s): Normal										
Landing Gear Type: Retractable	- Tricycle									
Amateur Built Acft? No Number of Seats: 5 Certified Max Gross Wt. 4400 LBS Numb								Number	er of Engines: 2	
Engine Type: Reciprocating	ngine Ma Continen	nufacturer: tal		Model/Se IO-360-0			ed Power: 0 HP			
- Aircraft Inspection Information										
Type of Last Inspection		Da	Date of Last Inspection Time Since Last Inspect				ection	ction Airframe Total Time		
100 Hour		C	4/2001				79 Ho	urs	35	590.1 Hours
- Emergency Locator Transmitter (ELT) Information									
ELT Installed?/Type Yes /		E	LT Operat	ed? No	ELT Aid	ded in Locatin	g Accide	nt Site?	No	
Owner/Operator Information		•								
Registered Aircraft Owner			Street A		aMaka (St.				
Skycraft Air Maintenance 73-1103 MakaMaka St. City State Zip Co								Zip Code		
Kailua Kona HI 96740										
On anaton of Aircraft			Street A							
Operator of Aircraft P.O. Box 830 Mokulele Flight Service Inc. City State Zip Code										Zin Code
Mokulele Flight Service, Inc.								HI	96725	
Operator Does Business As:					0	perator Desig	nator Co	de: MK	9A	
- Type of U.S. Certificate(s) Held:					-					
Air Carrier Operating Certificate(s):	On-demand Air T	axi								
Operating Certificate:				Operator Certifi	cate:					
Regulation Flight Conducted Under	r: Part 135: Air Ta	xi & Com	muter							
Type of Flight Operation Conducted				nger Onlv						
71 - 3										
]	FACTUA	L REPO	RT - AVIATION						Page 2

National Transportation Safety Board
FACTUAL REPORT
AVIATION

NTSB ID: LAX01LA181

Occurrence Date: 05/18/2001

	AVIATI	ON		Occurrence Type: Accident								
First Pilot	t Information											
Name City State Date of Birth									Age			
On File						On File				On File	On File	47
Sex: M	C: M Seat Occupied: Left Occupational Pilot? Civilian Pilot Certificate Number: On File											'
Certificate(s): Fligh	nt Instructor;	Commercia	al					•			
Airplane Rating(s): Multi-engine Land; Single-engine Land												
Rotorcraft/0	Glider/LTA: Glide	er										
Instrument	Rating(s): Airpl	ane										
Instructor F	Rating(s): Airpl	ane Single-	engine; Inst	rument Airp	olane							
Current Bie	nnial Flight Revie	ew? 11/2000)									
Medical Ce	rt.: Class 2	Medica	al Cert. Status	s: Valid Med	dicalno wa	ivers/lim.		Da	te of Las	t Medical	Exam: 05/200)1
		<u>'</u>						_				
- Flight Tim	ne Matrix	All A/C	This Make and Model	Airplane Single Engine	Airplane Mult-Engine	Night	Actual	Instrument	Simulated	Rotorcraf	t Glider	Lighter Than Air
Total Time		4400	249	4100	297	150)	35	140		20	0
Pilot In Cor	mmand(PIC)	4200	249	3900	280	140)	35	140		18	0
Instructor		2200		2200		100)	20	130			
Instruction	Received											
Last 90 Day	ys											
Last 30 Day										+		
Last 24 Ho						<u> </u>						
Seatbelt Used? Yes Shoulder Harness Used? Yes Toxicology Performed? N								? No		Second Pilot?	No	
Flight Plan/Itinerary												
	ght Plan Filed: Co	ompany VFI	R									
Departure Point State						te /	Airport I	oort Identifier Departure Time Time				
Kona HI KOA 0700								0	HST			
Destination State Airport Identifier												
Local Flight HI KOA												
Type of Clearance: None												
Type of Air	space: Class	G										
Weather	Information											
Source of \	Wx Information:											
	Flight	Service Sta	tion									
				FACTUAL	REPORT -	- AVIATIO	ON					Page 3

National Transportation Safety Board
FACTUAL REPORT

NTSB ID: LAX01LA181

Occurrence Date: 05/18/2001

	AVIATION		Occurrent	Occurrence Type: Accident								
Weather Information												
WOF ID	Observation Time	Time Zone	WOF Elevat	WOF Elevation WOF Distance From Acc			m Accid	dent Site		Direction Fro	om Accident S	site
ITO	0751	HST	38 Ft.	MQI				27 NM			310 De	a Mag
			30 Ft.	IVIOL	<u> </u>				g. iviay.			
Sky/Lowes	st Cloud Condition: Clear	<u>r</u>				Ft. A	GL	Condition of Light: Day				
Lowest Ce	eiling: None		Ft.	AGL	Visibi	lity:	10	SM	Alti	Itimeter: 30.08 "Hg		
Temperatu	ure: 23 °C I	Dew Point:	19 °C	Weatl	ner Condit	tions at Acc	cident S	Site: Visual	Cond	litions		
Wind Direc	ction: Variable	Wind Speed:	4		Wind	d Gusts:						
Visibility (R	RVR): Ft.	Visibility (RV	′V)	SM								
Precip and	d/or Obscuration:											
Accident	Information											
Aircraft Damage: Destroyed Ai			Aircraft Fir	Aircraft Fire: None				Aircraft Exp	olosio	n None		
- Injury Su	mmary Matrix	Fatal Seri	ious Mino	or	None	TOTAL						
First Pi	ilot				1	1	<u> </u>					
Second	d Pilot											
Studen	nt Pilot						7					
Flight I	Instructor						7					I
Check	Pilot						7					l
Flight E	Engineer						7					
Cabin A	Cabin Attendants											
Other C	Crew						7					
Passen	ngers				4		<u>-</u>					
- TOTAL A	ABOARD -				5	5	5					
Other C	Ground						7					
- GRAND	D TOTAL -				5	5	5					
		·										

National Transportation Safety Board

FACTUAL REPORT AVIATION

NTSB ID: LAX01LA181

Occurrence Date: 05/18/2001

Occurrence Type: Accident

	Information

Investigator-In-Charge (IIC)

TEALEYE C. CORNEJO

Additional Persons Participating in This Accident/Incident Investigation:

Dave Ryon Federal Aviation Administration Honolulu, HI